

DeviceMaster EIP | DeviceMaster UP Minimum Firmware Versions

Use the latest PortVision DX version with these firmware versions

TLA		Description	New MAC Address Range		Starting S/N	Minimum Bootloader Version	Minimum EtherNet/IP Version
1 Port	99441-1	DeviceMaster UP, DB9M, 5-30VDC, 1P, Panel	00 C0 4E 42 00 00	00 C0 4E 42 FF FF	9941-030000	4.00	6.02
	99601-9	EIP-2101 (DB9M)	00 C0 4E 5D 00 00	00 C0 4E 5D FF FF	9601-000001	4.25	6.02
	99620-0	EIP-2201 (Screw Terminal)	00 C0 4E 62 00 00	00 C0 4E 62 FF FF	9620-000001	4.00	6.02
2 Port	99551-7	EIP-2102 (DB9M, 1E)	00 C0 4E 46 00 00	00 C0 4E 46 FF FF	9551-003301	4.25	6.02
	99561-6	EIP-2302 (DB9M, 2E)	00 C0 4E 47 00 00	00 C0 4E 47 FF FF	9561-001101		
	99531-9	EIP-2202 (Screw Terminals, 1E)	00 C0 4E 44 00 00	00 C0 4E 44 FF FF	TBD		
	99541-8	EIP-2402 (Screw Terminals, 2E)	00 C0 4E 45 00 00	00 C0 4E 45 FF FF	TBD		
4 Port	99447-3	DeviceMaster UP, DB9/RJ45, 4P	00 C0 4E 48 00 00	00 C0 4E 48 FF FF	9447-030000	4.02	6.02
	99611-8	EIP-2304 (DB9M, 2E)	00 C0 4E 5C 00 00	00 C0 4E 5C FF FF	9611-000001	4.25	6.02

1/21/2019