

DeviceMaster MOD | DeviceMaster UP Minimum Firmware Versions

Use the latest PortVision DX version with these firmware versions

TLA		Description	New MAC Address Range		Starting S/N	Minimum Bootloader Version	Minimum Modbus Router Version	Minimum Modbus Server Version	Minimum Modbus TCP Version
1 Port	99501-2	DeviceMaster UP, DB9M, 5-30VDC, 1P, Panel	00 C0 4E 42 00 00	00 C0 4E 42 FF FF	9950-030000	4.00	6.06	6.02	6.03
	99606-6	MOD-2101 (DB9M)	00 C0 4E 5D 00 00	00 C0 4E 5D FF FF	9606-000001	4.25	6.06	6.02	6.03
	99621-7	EIP-2201 (Screw Terminal)	00 C0 4E 62 00 00	00 C0 4E 62 FF FF	9621-000001	4.00	6.06	6.02	6.03
2 Port	99552-4	MOD-2102 (DB9M, 1E)	00 C0 4E 46 00 00	00 C0 4E 46 FF FF	9552-003301	4.25	6.06	6.02	6.03
	99562-3	MOD-2302 (DB9M, 2E)	00 C0 4E 47 00 00	00 C0 4E 47 FF FF	9562-001101	4.25	6.06	6.02	6.03
	99532-6	MOD-2202 (Screw Terminals, 1E)	00 C0 4E 44 00 00	00 C0 4E 44 FF FF	TBD				
	99542-5	MOD-2402 (Screw Terminals, 2E)	00 C0 4E 45 00 00	00 C0 4E 45 FF FF	TBD				
4 Port	99521-0	DeviceMaster UP, DB9/RJ45, 4P	00 C0 4E 48 00 00	00 C0 4E 48 FF FF	9521-030000	4.02	6.06	6.02	6.03
	99612-5	MOD-2304 (DB9M, 2E)	00 C0 4E 5C 00 00	00 C0 4E 5C FF FF	9612-000001	4.25	6.06	6.02	6.03
16 Port	99582-1	DeviceMaster UP, 16P, RJ45	00 C0 4E 40 00 00	00 C0 4E 40 FF FF	9958-030000	4.00	6.06	6.02	6.03

1/21/2019