



ES8508/ES8508-XT Firmware History (1800428)

Changes from v2.0 to 2.1

- Added TACACS+ support.

Changes from v1.4 to 2.0

- Dropped Java requirement.
- Added service netvision disable command to the CLI.

Changes from v1.3c to v1.4

- Bootloader v1.5.1.7
- Flash memory update
- Add EtherNet/IP functionality
- Fix web PVLAN configuration bug
- Improve web page performance

Changes from v1.3b to v1.3c

- Update web interface with a signed JAR file so that Java 7/Update 51 permits the web interface to open.using the Java default security settings.
- Change pop up message when changing from an DHCP address to a static address.