

RocketLinx/Java 7 Update 7 Compatibility Issue Resolved

There was a known condition in which a user was unable to open the web server interface of RocketLinx managed switches. This condition occurred after Java Version 7 Update 51 (or higher) was installed in the PC and when using Java with the default browser security settings. Previous versions of Java did not exhibit this behavior.

Control has released firmware that works with Java Version 7 Update 51 and higher. These products **are** currently compatible with Java Runtime Environment (Version 7 Update 51 or higher) when the **latest firmware version is successfully uploaded onto the RocketLinx switch.**

Please note the following list specifies the firmware version in which this issue was originally resolved (the existing version may be higher) and provides a link to the file download location:

- ES7506 [v2.3](#)
- ES7510 [v1.3b](#)
- ES7510-XT [v1.3b](#)
- ES7528 [v1.4a](#)
- ES8508 [v1.3c](#)
- ES8508F [v1.3c](#)
- ES8509-XT [v1.4](#)
- ES8510/ES8510-XT [v2.7b](#)
- E8510-XTE [v2.7a](#)
- ES9528/ES9528-XT [v1.4a](#)